



A number line is shown with tick marks at 0, 20, 40, and 80. The label "(feet)" is centered below the line. A shaded region is marked between the 20 and 40 tick marks.

PAC TRUST KUEBLER DEVELOPMENT
MEDICAL OFFICE

PAC TRUST KUEBLER DEVELOPMENT

MEDICAL OFFICE

EXISTING CONDITIONS PLAN

DRAWING
C1.0

JOB NUMBER
2672.XXXX.0

VERIFY SCALE
BAR IS ONE INCH ON
ORIGINAL DRAWING

1"

IF NOT ONE INCH ON
THIS SHEET, ADJUST
SCALES ACCORDINGLY

VERIFY SCALE	
BAR IS ONE INCH ON ORIGINAL DRAWING	
IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY	
CDN.	JW
DRN.	MDP
CKD.	JW

REVIEW

PROFESSIONAL ENGINEER
 WILLIAM T. WELLS
 OREGON
 NO. 64517
 NOV. 12, 2008
 RENEWS: 6/30/2012

WE

WESTECH ENGINEERING, INC.
CONSULTING ENGINEERS AND PLANNERS

1841 Farview Industrial Dr. S.E., Suite 100, Salem, OR 97302
Phone: (503) 585-2474 Fax: (503) 585-3966
E-mail: westech@westech-eng.com