

## PROPERTY LINE ADJUSTMENT

A TRACT OF LAND LOCATED IN THE
NW ONE-QUARTER OF SECTION 11,
TOWNSHIP 8 SOUTH, RANGE 3 WEST, WILLAMETTE MERIDIAN,
CITY OF SALEM, MARION COUNTY, OREGON
JANUARY 13, 2023
DR HORTON

NARRATIVE

THE PURPOSE OF THIS SURVEY IS TO ADJUST THE COMMON LINES OF THOSE PROPERTIES DESCRIBED AS PARCEL I AND II IN THAT DEED RECORDED IN REEL 1329, PAGE 308, MARION COUNTY DEED RECORDS, AS DIRECTED BY THE CLIENT, IN ANTICIPATION OF A FUTURE SUBDIVISION.

THIS PLAT IS SUBJECT TO THE CITY OF SALEM CONDITIONS OF APPROVAL CASE NUMBER PLA23-\_\_\_\_\_.

THE BOUNDARY LINES ARE HELD PER EMERIO DESIGN'S PREVIOUSLY RECORDED RECORD OF SURVEY 39539, MARION COUNTY SURVEY RECORDS.

## NOTE:

MONUMENT #44 WAS SET BY THE COUNTY SURVEYOR PER THEIR DETERMINATION AND WILL BE REPLACED WITH A PERMANENT MONUMENT WHEN THE ANTICIPATED SUBDIVISION STREET CONSTRUCTION IS COMPLETED. FINAL PAVING AND THE PLACEMENT OF A MONUMENT BOX WILL BE COORDINATED WITH THE MARION COUNTY SURVEYOR.

## NOTES

1. FENCES NOT RELATED TO POSSIBLE LINES OF POSSESSION EXIST BUT ARE NOT DEPICTED.

- 2. NO FENCES OR WALLS ENCROACH ONTO THE SUBJECT PROPERTY FROM ANY ADJOINING PROPERTIES.
- 3. FENCES LOCATED ON THE SUBJECT PROPERTY DO NOT ENCROACH ONTO ANY ADJOINING PROPERTIES AND ARE TO BE REMOVED DURING FUTURE DEVELOPMENT.

# MONUMENT TABLE

- 05 FOUND 1/2" IRON PIPE PER (4) N88°09'28"W, 0.14' FROM RIGHT OF WAY LINE
- D6 FOUND 1/2" IRON PIPE REF'D IN (4) N88°09'28"W, 0.23' FROM DEDICATION LINE
- O8 FOUND 2" AL DISK W/ PUNCH MARKED "CITY OF SALEM" PER (7) HELD FOR PT OF CURVE
- 09 FOUND 1-1/2" IRON PIPE DN 0.5' SW CORNER DLC 41 HELD FOR CL
- 10 FOUND 2" AL DISK W/ PUNCH MARKED "CITY OF SALEM" PER (7) HELD FOR PC OF CURVE
- 11 FOUND 1/2" IRON ROD
  PER (4)
  S01°49'37"W, D.13' FROM BOUNDARY
  HELD FOR CENTERLINE
- FOUND RR SPIKE BENT NE - DN 0.2 PER (9)
- 16 FOUND 1/2" IRON PIPE BENT SE - DN 0.7' PER (1) \$88"29'31"E, 0.72' FROM RIGHT OF WAY
- 17 FOUND 1/2" IRON PIPE UP 0.3' PER (1) HELD FOR WESTERLY RIGHT OF WAY
- 19 FOUND 1" IRON PIPE BENT NW - DN 0.2' PER (8) N56°27'37"W, 0.79' FROM NW CORNER
- 20 FOUND 1" IRON PIPE DN 0.2' PER (3) \$25'46'33"W, 0.82' FROM RIGHT OF WAY AT BOUNDARY

- 21 FOUND 1" IRON PIPE DN 0.3' PER (2) N88°29'31"W, 0.21' FROM RIGHT OF WAY
- 22 FOUND 1" IRON PIPE BENT, BROKEN UP 0.1' PER (2)

23

- ON RIGHT OF WAY LINE
  FOUND 2" IRON PIPE
- DN 0.1' PER (10) ON RIGHT OF WAY LINE
- 24 FOUND 1/2" IRON PIPE UP 0.3' PER (5) N02°31'56"E, 0.31' FROM RIGHT OF WAY
- 25 FOUND 1/2" IRON PIPE DN 0.4' PER (5) N02°31'56"E, 0.23' FROM RIGHT OF WAY
- 26 FOUND 5/8" IRON ROD DN 0.4'
  PER (5)
  ON RIGHT OF WAY LINE
- 27 FOUND 5/8" IRON ROD DN 0.4' PER (5) ON RIGHT OF WAY LINE
- 29 FOUND 1" IRON PIPE DN 0.4" PER MCSR 6237 HELD FOR SE CORNER
- 30 FOUND BOLT UP 0.5' NO RECORD
- 31 FOUND 1/2" IRON PIPE PER (4) S01°50'32"W, 0.05' FROM BOUNDARY
- 32 FOUND 1/2" IRON PIPE PER (4) \$01°50'32"W, 0.06' FROM BOUNDARY
- FOUND 1" IRON PIPE DN 1.0' PER (2) N88°29'31"W, 0.38' FROM RIGHT OF WAY

- 34 FOUND 1" IRON PIPE DN 0.5' PER (2) N88°29'31"W, 0.67' FROM RIGHT OF WAY
- 35 FOUND 1/2" IRON PIPE DN 0.3' PER (2) N88°29'31"W, 0.81' FROM RIGHT OF WAY
- 36 FOUND 1/4" IRON ROD DN 0.5' NO RECORD S88"29'31"E, 0.08' FROM RIGHT OF WAY
- 37 FOUND 1/4" IRON ROD
  DN 1.0'
  NO RECORD
  1.61' NORTH AND 0.89' WEST OF RIGHT OF WAY LINES
- 38 FOUND 1/2" IRON PIPE DN 1.0' PER (1) \$88"29"31"E, 0.03' FROM RIGHT OF WAY
- 41 FOUND 1/4" IRON ROD DN 1.0' NO RECORD 588"29'31"E, 0.15' FROM RIGHT OF WAY
- 42 FOUND RR SPIKE NO RECORD S88\*29'31"E, 3.75' FROM RIGHT OF WAY NOT USED
- FOUND YPC MARKED
  "MARION COUNTY SURVEYOR"
  HELD FOR SW CORNER
  PER MCSR 39415
- 45 FOUND 5/8" IRON ROD DN 0.3' HELD EAST / WEST, 0.03' NORTH OF BOUNDARY LINE PER MCSR 33941
- 46 FOUND YPC UNREDABLE FALLS \$58°11'53"W 0.04' FROM PARCEL 2 CORNER PER (5)
- 47 FOUND 1/2" IRON PIPE FALLS N88°07'07"W 0.22' WEST OF BOUNDARY LINE NO RECORD



OREGON JULY 12, 2005 ERIC D. LYNCH 56544 EXPIRES 12-31-24



6445 SW FALLBROOK PLACE, SUITE 100 BEAVERTON, OREGON 97008 TEL: (503) 746-8812 FAX: (503) 639-9592 www.emeriodesign.com EMERIO JOB: 0883-004 PAGE 2 OF 2