## Action Drain and Rooter Service

3690 Kashmir Way SE Salem, OR 97317

503-370-7321 BILL TO: Nick Oleskiewicz

Invoice: 206840

DATE: 8/17/2023

Service Tech: Cory

Jess 932-2401

P.O.	NU	IMB	ER:	

TERMS:

Upon Receipt

DESCRIPTION	AMOUNT
2254 Shiloh Ct SE	
*Video Inspection Video Inspect 3" storm drain from the curb outlet on North side of the driveway approach, about 60' to the NE corner of house.	180.00
Could not get beyond the NE corner, as the drain appears to be blocked by root intrusion and other debris.	
Also Inspected from a drain on the East side of the house, near the AC unit.	
Found 3" PVC is broken under back concrete area and has root intrusion. Recommend repairing drain. Tree may need removed to prevent further damage to drainage system.	
Video Inspection Links: https://youtu.be/li0eJy77FYw https://youtu.be/eiNom_bMZKc	